



Nissan Service Information Bulletin

TechMate Tools and Equipment

HRK Connector Repair Parts Transition

Reference: NSIB/22-001

Date: May 2022

Beginning in May 2022, NNA will no longer sell wiring harness connector repair parts through the TechMate tools and equipment program. Instead, those items will transition to Nissan Service Parts that will be found here:

<https://vcat.nnanet.com/prweb/PRAuth/Connectors>


In order to add your existing connector repair parts (from the Harness Repair Kit, part of your Dealer's essential tools kit) into your dealership's DMS inventory, each Harness Repair Kit connector repair part has now been assigned a new Nissan Service Part number (which replaces the old "J-" number).

Once added to your DMS inventory, these parts can become ASR managed and therefore replenished by ASR after they have met phase-in criteria.

What you need to do:

- Included in this package are pre-printed Nissan Service Part number labels
- Reference the table below to re-label your existing connector repair parts inventory with their new Service Part numbers
- You can use the Harness Repair Kit mobile app (Nissan HRK) to identify any parts that are not labeled or missing a label
- Add those new parts and their respective on hand counts to your DMS inventory
- Note that any TechMate "J-" number that is not listed below is obsolete and will not be issued a Nissan service part number

Note: The old parts with a TechMate "J-" number for the connector pigtail and the new Nissan service part assemblies do not look the same due to an inventory running change but will have the same part number.





Nissan Service Information Bulletin

TechMate Tools and Equipment

HRK Connector Repair Parts Transition

Reference: NSIB/22-001

Date: May 2022

Nissan Tool Kit Relabeling Reference Chart		
OLD Harness Repair Kit Tray Location	OLD Tool Number	New Service Part#
1	J-48817-101	24008 9DM2A
1	J-48817-102	24008 9DM2B
1	J-48817-103	24008 9DN1C
1	J-48817-104	24008 9DM0A
1	J-48817-106	24008 9DM2D
1	J-48817-107	24008 9DM2E
1	J-48817-108	24008 9DM3A
1	J-48817-109	24008 9DM0B
1	J-48817-110	24008 9DM3B
1	J-48817-111	24008 9DM3C
1	J-48817-112	24008 9DM3D
2	J-48817-113	24008 9DM3E
2	J-48817-114	24008 9DM4A
2	J-48817-116	24008 9DM0C
2	J-48817-117	24008 9DM4C
2	J-48817-118	24008 9DM4D
2	J-48817-119	24008 9DM4E
2	J-48817-120	24008 9DM5A
2	J-48817-121	24008 9DM0A
2	J-48817-122	24008 9DM5B
2	J-48817-123	24008 9DM5C
2	J-48817-124	24008 9DM5D
3	J-48817-125	24008 9DM3B
3	J-48817-126	24008 9DM5E
3	J-48817-127	24008 9DM6A
3	J-48817-128	24008 9DM6B
3	J-48817-129	24008 9DM6C
3	J-48817-130	24008 9DM6D
3	J-48817-131	24008 9DM6E



Nissan Service Information Bulletin

TechMate Tools and Equipment

HRK Connector Repair Parts Transition

Reference: NSIB/22-001

Date: May 2022

OLD Harness Repair Kit Tray Location	OLD Tool Number	New Service Part#
3	J-48817-132	24008 9DM7A
3	J-48817-133	24008 9DM1E
3	J-48817-134	24008 9DM7B
3	J-48817-135	24008 9DM4A
3	J-48817-136	24008 9DM7C
4	J-48817-137	24008 9DM7D
4	J-48817-139	24008 9DN1B
4	J-48817-140	24008 9DM8A
4	J-48817-141	24008 9DM8B
4	J-48817-142	24008 9DM8C
4	J-48817-143	24008 9DM8D
4	J-48817-144	24008 9DM8E
4	J-48817-145	24008 9DE9A
4	J-48817-146	24008 9DM9B
5	J-48817-201	24008 9DJ8A
5	J-48817-202	24008 9DJ8B
5	J-48817-203	24008 9DJ8C
5	J-48817-204	24008 9DJ8D
5	J-48817-205	24008 9DJ8E
5	J-48817-206	24008 9DJ9A
5	J-48817-207	24008 9DJ9C
5	J-48817-208	24008 9DJ9C
5	J-48817-209	24008 9DJ9D
5	J-48817-210	24008 9DJ3D
5	J-48817-211	24008 9DJ2A
5	J-48817-212	24008 9DJ2B
6	J-48817-213	24008 9DJ2C
6	J-48817-214	24008 9DJ8D
6	J-48817-215	24008 9DJ2E
6	J-48817-216	24008 9DJ3A



Nissan Service Information Bulletin

TechMate Tools and Equipment

HRK Connector Repair Parts Transition

Reference: NSIB/22-001

Date: May 2022

OLD Harness Repair Kit Tray Location	OLD Tool Number	New Service Part#
6	J-48817-217	24008 9DJ3B
6	J-48817-218	24008 9DJ3C
6	J-48817-219	24008 9DJ3D
6	J-48817-220	24008 9DJ3E
6	J-48817-221	24008 9DJ4A
6	J-48817-222	24008 9DJ4B
6	J-48817-223	24008 9DJ4C
6	J-48817-224	24008 9DL9C
7	J-48817-227	24008 9DJ5A
7	J-48817-228	24008 9DJ5B
7	J-48817-229	24008 9DJ5C
8	J-48817-161	24008 9DM9E
8	J-48817-162	24008 9DN3A
8	J-48817-163	24008 9DN3B
8	J-48817-164	24008 9DN3C
8	J-48817-165	24008 9DN3D
9	J-48817-149	24008 9DM9D
9	J-48817-150	24008 9DM1B
9	J-48817-151	24008 9DM9E
9	J-48817-152	24008 9DN2A
9	J-48817-153	24008 9DM1C
9	J-48817-154	24008 9DN2B
9	J-48817-155	24008 9DN0B
9	J-48817-157	24008 9DN2C
9	J-48817-159	24008 9DN2E
9	J-48817-160	24008 9DN1A
10	J-48817-236	24008 9DJ5D
10	J-48817-238	24008 9DL6B
10	J-48817-239	24008 9DJ5E
10	J-48817-240	24008 9DJ6A



Nissan Service Information Bulletin

TechMate Tools and Equipment

HRK Connector Repair Parts Transition

Reference: NSIB/22-001

Date: May 2022

OLD Harness Repair Kit Tray Location	OLD Tool Number	New Service Part#
10	J-48817-241	24008 9DJ6B
11	J-48817-166	24008 9DN3E
11	J-48817-167	24008 9DN4A
11	J-48817-168	24008 9DN4B
11	J-48817-169	24008 9DN4C
11	J-48817-170	24008 9DN4D
11	J-48817-171	24008 9DN4E
11	J-48817-172	24008 9DN5A
11	J-48817-173	24008 9DM4D
11	J-48817-174	24008 9DN5C
11	J-48817-175	24008 9DN5D
11	J-48817-176	24008 9DN5E
11	J-48817-242	24008 9DJ6C
11	J-48817-243	24008 9DL8A
13	J-48817-177	24008 9DN1E
13	J-48817-178	24008 9DN6A
13	J-48817-179	24008 9DN6B
13	J-48817-180	24008 9DN6C
13	J-48817-181	24008 9DM1D
13	J-48817-182	24008 9DN6D
13	J-48817-183	24008 9DN6E
13	J-48817-184	24008 9DN7A
13	J-48817-185	24008 9DM0B
13	J-48817-186	24008 9DN7C
13	J-48817-187	24008 9DN7D
13	J-48817-188	24008 9DN7E
14	J-48817-244	24008 9DJ6E
14	J-48817-245	24008 9DJ7A
14	J-48817-246	24008 9DJ7B
14	J-48817-247	24008 9DJ7C



Nissan Service Information Bulletin

TechMate Tools and Equipment

HRK Connector Repair Parts Transition

Reference: NSIB/22-001

Date: May 2022

OLD Harness Repair Kit Tray Location	OLD Tool Number	New Service Part#
14	J-48817-248	24008 9DJ7D
14	J-48817-249	24008 9DJ7E
14	J-48817-253	24008 9DL9A
14	J-48817-254	24008 9DL9B
14	J-48817-255	24008 9DJ2E
14	J-48817-256	24008 9DL9D
14	J-48817-257	24008 9DL9E
14	J-48817-259	24008 9DJ4E
15	J-48817-1101	24008 9DN9E
15	J-48817-189	24008 9DN8A
15	J-48817-190	24008 9DN8B
15	J-48817-191	24008 9DN8C
15	J-48817-192	24008 9DN8D
15	J-48817-193	24008 9DN8E
15	J-48817-194	24008 9DN9A
15	J-48817-195	24008 9DN9B
15	J-48817-196	24008 9DN3D
15	J-48817-197	24008 9DN9C
15	J-48817-198	24008 9DN9D
15	J-48817-199	24008 9DN0C
16	J-48817-1102	24008 9DM1A
16	J-48817-1103	24008 9DM0D
16	J-48817-1104	24008 9DM0E
16	J-48817-1105	24008 9DK0A
16	J-48817-1106	24008 9DK0B
16	J-48817-1107	24008 9DK0C
16	J-48817-1108	24008 9DK0D
16	J-48817-1109	24008 9DK0E
16	J-48817-1110	24008 9DK1A
16	J-48817-1111	24008 9DK1B



Nissan Service Information Bulletin

TechMate Tools and Equipment

HRK Connector Repair Parts Transition

Reference: NSIB/22-001

Date: May 2022

OLD Harness Repair Kit Tray Location	OLD Tool Number	New Service Part#
16	J-48817-1112	24008 9DK1C
16	J-48817-1113	24008 9DK1D
17	J-48817-1114	24008 9DK1E
17	J-48817-1115	24008 9DK2A
17	J-48817-1116	24008 9DK2B
17	J-48817-1117	24008 9DK2C
17	J-48817-1118	24008 9DK2D
17	J-48817-1119	24008 9DK2E
17	J-48817-1120	24008 9DK3A
17	J-48817-1121	24008 9DK3B
17	J-48817-1122	24008 9DK3C
17	J-48817-1123	24008 9DK3D
17	J-48817-1124	24008 9DK3E
17	J-48817-1125	24008 9DK4A
18	J-48817-261	24008 9DL8A
18	J-48817-263	24008 9DL8B
18	J-48817-266	24008 9DL8C
18	J-48817-267	24008 9DJ2C
18	J-48817-268	24008 9DL8E
18	J-48817-269	24008 9DL7A
18	J-48817-270	24008 9DL7B
18	J-48817-274	24008 9DL6C
21	J-48817-1157	24008 9DE0B
21	J-48817-1158	24008 9DE0C
21	J-48817-1159	24008 9DE0D
21	J-48817-1160	24008 9DE0E
21	J-48817-1161	24008 9DE1A
21	J-48817-1162	24008 9DE1B
21	J-48817-1163	24008 9DE1C
21	J-48817-1164	24008 9DE1D



Nissan Service Information Bulletin

TechMate Tools and Equipment

HRK Connector Repair Parts Transition

Reference: NSIB/22-001

Date: May 2022

OLD Harness Repair Kit Tray Location	OLD Tool Number	New Service Part#
21	J-48817-1165	24008 9DE1E
21	J-48817-1166	24008 9DE2A
21	J-48817-1167	24008 9DE2B
21	J-48817-1168	24008 9DE2C
22	J-48817-1169	24008 9DE2D
22	J-48817-1170	24008 9DE2E
22	J-48817-1171	24008 9DE3A
22	J-48817-1172	24008 9DE3B
22	J-48817-1173	24008 9DE3C
22	J-48817-1174	24008 9DE3D
22	J-48817-1175	24008 9DE3E
22	J-48817-1176	24008 9DE4A
22	J-48817-1177	24008 9DE4B
22	J-48817-1178	24008 9DE4C
22	J-48817-1180	24008 9DE4E
22	J-48817-1181	24008 9DE5A
23	J-48817-2002	24008 9DL3B
23	J-48817-2003	24008 9DL3C
23	J-48817-2005	24008 9DL6D
23	J-48817-2006	24008 9DL3D
23	J-48817-2007	24008 9DL3E
23	J-48817-2008	24008 9DL2D
23	J-48817-2009	24008 9DL2E
23	J-48817-2010	24008 9DL6E
24	J-48817-1183	24008 9DE5C
24	J-48817-1184	24008 9DE5D
24	J-48817-1185	24008 9DE5E
24	J-48817-1186	24008 9DE6A
24	J-48817-1187	24008 9DE6B
24	J-48817-1189	24008 9DE6D



Nissan Service Information Bulletin

TechMate Tools and Equipment

HRK Connector Repair Parts Transition

Reference: NSIB/22-001

Date: May 2022

OLD Harness Repair Kit Tray Location	OLD Tool Number	New Service Part#
24	J-48817-1191	24008 9DE7A
24	J-48817-1192	24008 9DE7B
24	J-48817-1182	24008 9DE5B
24	J-48817-1188	24008 9DE6C
24	J-48817-1193	24008 9DE7C
25	J-48817-1194	24008 9DE7D
25	J-48817-1197	24008 9DE8B
25	J-48817-1198	24008 9DE8C
25	J-48817-1199	24008 9DE8D
25	J-48817-1195	24008 9DE7E
25	J-48817-1200	24008 9DE8E
25	J-48817-1201	24008 9DN0D



Nissan Service Information Bulletin

TechMate Tools and Equipment

HRK Connector Repair Parts Transition

Reference: NSIB/22-001

Date: May 2022