

The job GM-35616-300-B contains the each the following:

- | | | |
|----------------------------|----------------------------|-----------------------------|
| 1. GM-35616-58 (1 PROBE) | 13. GM-35616-16 (2 PROBES) | 25. GM-35616-40 (1 PROBE) |
| 2. GM-35616-2A (1 PROBE) | 14. GM-35616-17 (2 PROBES) | 26. GM-35616-41 (1 PROBE) |
| 3. GM-35616-3 (1 PROBE) | 15. GM-35616-18 (2 PROBES) | 27. GM-35616-42 (1 PROBE) |
| 4. GM-35616-4A (1 PROBE) | 16. GM-35616-19 (2 PROBES) | 28. GM-35616-43 (1 PROBE) |
| 5. GM-35616-5 (1 PROBE) | 17. GM-35616-21 (2 PROBES) | 29. GM-35616-44 (1 PROBE) |
| 6. GM-35616-6 (1 PROBE) | 18. GM-35616-22 (2 PROBES) | 30. GM-35616-45 (1 PROBE) |
| 7. GM-35616-8 (1 PROBE) | 19. GM-35616-31 (2 PROBES) | 31. GM-35616-54 (2 PROBES) |
| 8. GM-35616-9 (1 PROBE) | 20. GM-35616-32 (2 PROBES) | 32. GM-35616-56 (2 PROBES) |
| 9. GM-35616-10 (2 PROBES) | 21. GM-35616-33 (2 PROBES) | 33. GM-35616-64B (2 PROBES) |
| 10. GM-35616-12 (2 PROBES) | 22. GM-35616-34 (2 PROBES) | 34. GM-35616-65B (2 PROBES) |
| 11. GM-35616-13 (2 PROBES) | 23. GM-35616-35 (2 PROBES) | 35. GM-35616-66 (2 PROBES) |
| 12. GM-35616-14 (2 PROBES) | 24. GM-35161-37 (2 PROBES) | |

{Probes are marked per their overall drawing}

PACKAGING REQUIREMENTS:

1. PLACE ALL ITEMS LISTED ABOVE INTO STORAGE CASE W/FOAM#C005-118X3X-02A-FOAM.
2. THE STORAGE CASE GETS A DECAL#D001-GM35616-300B.
3. PLACE CASE INTO SHIPPING BOX #B022-11X9X4-01
4. THE SHIPPING BOX IS MARKED:

GM-35616-300-B

TERMINAL PROBE KIT

COO: US



 Warning: Cancer and Reproductive Harm www.P65Warnings.ca.gov